

Oil Field Environmental Incident Summary

Incident: 20150302120112 **Date/Time of Notice:** 03/02/2015 12:01

Responsible Party: MARATHON OIL COMPANY

Well Operator: MARATHON OIL COMPANY

Well Name: DICKEY 11-30TFH

Field Name: REUNION BAY

Well File #: 28268

Date Incident: 3/2/2015 **Time Incident:** 05:05

Facility ID Number:

County: MOUNTRAIL

Twp: 151

Rng: 93

Sec: 25

Qtr:

Location Description:

Submitted By: Chris Gitch

Received By:

Contact Person: Christopher Gitch
3172 HWY 22 N
DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5.6	Barrels	5.6	Barrels	5.69	barrels

Description of Other Released Contaminant:

Frac Fluid

Inspected:

Written Report Received: 3/11/2015

Clean Up Concluded: 2/2/2015

Risk Evaluation:

No immediate Risk. Spill has been cleaned up

Areal Extent:

Potential Environmental Impacts:

No potential environmental impacts. Spill has been cleaned up

Action Taken or Planned:

Spill was cleaned up by vac truck on location. Failed valve was isolated upstream

Wastes Disposal Location: Wastes disposed of at approved facility by contractor

Agencies Involved:

Updates

Date: 3/2/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.